


SA02XPQC-MCL



XP SpaceArm Quick Change Double Hub Large Mini Clamp




adapt
Deutschland



Required Tools:
17 mm Socket
5mm Allen Key
#2 Phillips Screwdriver



Adjusting Counter Balance
*Required Tool: 5mm Allen Wrench



Position Arm so it is parallel to desk surface.
Turn bolt clock wise for lighter monitors.

Cable Routing

